

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection: OGM Joe Helfrich Environmental Scientist III Company Johnny Pappas Sr. Environmental Engineer

Inspection Report

Permit Number:	C0070004
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, January 21, 2004
Start Date/Time:	01/21/2004 9:00:00 AM
End Date/Time:	01/21/2004 2:00:00 PM
Last Inspection:	Thursday, December 04, 2003

Inspector: Joe Helfrich, Environmental Scientist III

Weather: Sunny 30

InspectionID Report Number: 157

Reprocessing

Accepted by: dhaddock 01/27/2004

Permitee: CASTLE GATE HOLDING CO
Operator: CASTLE GATE HOLDING CO

Site: CASTLE GATE MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Mineral Ownership	Types of Operations		
✓ Federal	✓ Underground		
✓ State	Surface		
☐ County	✓ Loadout		
✓ Fee	✓ Processing		

7,619.00 Total Permitted
63.00 Total Disturbed
29.20 Phase I
18.20 Phase II
Phase III

Current Acreages

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Other

The purpose of this site visit was to conduct a partial inspection of the Castle Gate facilities.

Joe Helfrich, Environmental Scientist III

Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining



Permit Number: C0070004 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 21, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation	✓		✓	
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing	✓		✓	
16.	b Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070004 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 21, 2004

Page 3 of 3

2. Signs and Markers

The sign at the #1 Adit was posted with the correct information.

3. Topsoil

The topsoil used in reclamation of the #1Adit is stable and shows no signs of erosion.

13. Revegetation

The vegetation at the #1 is covered mostly by 6-10" of snow. Some of the pocked areas are exposed. The fourwing salt bush is, for the most part, the only vegetative species that can be seen.

16.a Roads: Construction, Maintenance, Surfacing

The road to the Hardscrabble site was blocked with snow several hundred yards past the railroad tracks. If some melting occurs during the next month the site may be accessible.